



PF2150-F

SOFTWARE RELEASE NOTES

Version 1.0

PF2150-F

CONTENTS

CONTENTS1

1. INTRODUCTION.....2

 SCOPE2

 KNOWN SAFETY ISSUES.....2

2. RELEASE NOTES3

 F 1.1.0.....3

 Changes3

 F 1.0.5.....3

 New.....3

 Changes3

 Fixes.....3

1. INTRODUCTION

SCOPE

This document is meant to provide customers with a list of changes for each software bundle release for the PF2150-F Flare Controller. The notes are categorized by their software bundle release version in the form E A.B.C, where:

A: Major Software Release (typically with new features)

B: Minor Software Release (typically with fixes / changes)

C: Build Number (internal use only)

Modification to software is generally split up into three main categories:

NEW: Software modifications that add additional functionality (e.g. features).

CHANGES: Software modifications which modify existing behavior.

FIXES: Software modifications which correct identified issues (e.g. bugs).

KNOWN SAFETY ISSUES

NONE

2. RELEASE NOTES

F 1.1.0

Change to HEI ignition behavior. Released September 25, 2026

CHANGES

- Updated HEI ignition behavior so the spark output remains continuously active while the coil is on, rather than cycling on and off

F 1.0.5

Initial PF2150-F release. Released on August 29, 2025.

NEW

Initial release

CHANGES

Initial release

FIXES

Initial release