

PF2150-E

SOFTWARE RELEASE NOTES

Version 4.0



PF2150-E SOFTWARE RELEASE NOTES

2/18/2025 v4.0



CONTENTS

CO	CONTENTS1		
1.			
	SCOPE		
	KNOWN SAFETY ISSUES		
2.	RELEASE NOTES		
	E 1.3.1		
	Fixes		
	E 1.3.0.		
	New		
	Changes		
	Fixes		

2/18/2025 v4.0



1. INTRODUCTION

SCOPE

This document is meant to provide customers with a list of changes for each software bundle release for the PF2150-E BMS Controller. The notes are categorized by their software bundle release version in the form E A.B.C, where:

A: Major Software Release (typically with new features)

B: Minor Software Release (typically with fixes / changes)

C: Build Number (internal use only)

Modification to software is generally split up into three main categories:

NEW: Software modifications that add additional functionality (e.g. features).

CHANGES: Software modifications which modify existing behavior.

FIXES: Software modifications which correct identified issues (e.g. bugs).

KNOWN SAFETY ISSUES

NONE

PF2150-E SOFTWARE RELEASE NOTES

2/18/2025 v4.0



2. RELEASE NOTES

E 1.3.1

Minor bug fixes. Released Feb 11, 2025.

FIXES

• Fixed a bug on the home screen where setpoint values would be displayed as Celsius values with Fahrenheit units when the system was configured in Fahrenheit.

E 1.3.0

Initial PF2150-E release. Released on December 4, 2024.

NEW

Initial release

CHANGES

Initial release

FIXES

Initial release